P24

App. F. IX-4

1929. (Imperial)

File No. 249-29

Serial Nos. 1-3 & 8
1, 2, 5 & 8

Previous References

Imp 392-26-17
" 135-23-8, 9, 12, 14
" 281-30 Sec 1-4

Later References

3,04-31 811-6.

General and Revenue Secretariat.

Serial Nos. 4

Part B for June 1930

SUBJECT

Requests sanction to the existing special establishment at Belur being increased by one more mason on Rs 40/- p m & two more coolies on Rs 15/- p m each.

H.O. dtd 27.6.-9 — To the Chief Engr. Etc
dated 7.6.30

Sanctioned for a period of two ~~three~~ years

General and Revenue Secretariat. 2 3 File No. 249 of 1929.

Serial No.	
1	Letter No 9678 dated the 8th February 1930 from the Chief Engineer of Mysore requesting sanction to the special establishment at Belur being increased one more mason on Rs 4 per mensem and two coolies on Rs 15/- each per mensem with an additional money of Rs 500/- per annum for materials.
Flag M	In Govt order No 854-61 Immg dt 392-26-6 dated the 24th Nov 1927 a special establishment was for the repairs and of the temples at Belur & Halebid and since it found that the entire establishment can in the absence of [illegible] for employment at Belur a separate establishment [illegible] for the Halebid temple Govt no 2775-77/ Immg 431-2 dated the 20th June 27
Flag L	

NOTE—Contn. sheet.

WD 066—GPB—80,000—26-7-29

General and Revenue Secretariat.

File No. 269 of 1929

Serial No.

According to the statement of Claims furnished in letter No 15-38 dated the 19th 24th June 1929 from the Asst Engineer Sakleshpur, to the Executive Engineer, Hassan Division, it is seen that an expenditure of Rs 2060/- is now being incurred on account of Spl establishment at the Belur Temple.

This establishment is recommended to be sanctioned by the addition of one mason on Rs 40/- a month and two more coolies on Rs 15/- each for one season, with an additional Money Grant of Rs 500/- for purchase of materials. Submitted for orders

CE, 19/7/30.

SE 20/7

The M.C may be informed

The proposal is hereby sanctioned

(Mr Menlies) 4/8

Yes. Has the Spl staff allowed for restoration of Halebid temple been engaged and have any reports been received

Work done

LIBRARY 2 FEB 1987 B

NOTE—Contn. sheet.

WD/066—GPB—30,000—26-7-29

General and Revenue Secretariat

File No. 24 7 of 1927

Serial No.

1) Draft calling for the M. C.S opinion is submitted for approval.

2) As the members orders about the entertainment of the Special staff allowed for the Hardinge temple, it is submitted that the first report on the subject of the action taken about giving effect to the Govt orders about this institution was received from the Chief Engineer on 28.12.27, and submitted to the Hon'ble Minister for Sanj on the same day. The file is not readily traceable, and will be searched for & submitted after the present difficulties

CE, 27/2/28 Hon 27/2

9 1) Hon 10 2) Papers submitted for perusal

To the Mess Comm—
2. No 1814 S. 3-3-30
Calls for his opinion on the Chief engineers proposals in
11 Refer to scheme of the Govt
Secy at para to of the H

Note—Contn. Sheet

WD 066—GPB—30,000—26-7-29

General and Revenue Secretariat

File No. 249 of 1929.

Serial No.

11382

Letter to Inspector General Communications
Iraq Area File No 431 of 1928 Pts
6 and 7 enclosing to the Inspector
General report on the execution of
repairs &c to the Hardstand
as put up below for Lucknow
C.E. 13 In this office letter No
4/3/30 1502 dated the 25th July
1930 the Chief Engineer has
been requested to forward
the Inspector General report for the
Quarter ending 31st December
1929
C.E.
14/3/30

Sig A
Division

2

Sig
4/3

(1st Number)

5412

Sig A
C.E.
15/3/30
Sig
17/3

28
4/3
2
11/3/30
14 (Times)
13.3.30

Note—Contn. Sheet

WD 066—GPB—80,000—26-7-29

1797

App. F. III—2

General and Revenue Secretariat — File No. 249 of 1929.

Serial No.

3 Letter No 1797/29-30 dated the 9th/10th May 1930 from the Executive Engineer Mysore reporting that the additional sum of Rs 1360/- required for the early completion of the repairs and renovation of the Belur temple may be allowed to be met from the Sheikh General Inam Fund Grant for construction & repairs of Inam institutions, in addition to the sum of Rs 2000 already sanctioned from the same source for the same purpose

15 submitted for orders with reference to orders of the Hon'ble Minister [illegible]

2/6 1181

15/5/30

14431 / 1930

FINANCE 2 JUNE 1930 7292

Note—Contn. Sheet

16 May be sanctioned for a period of 2 years for the [illegible] purposes. (Executive Engineer reports should be continued when submitted)

1/6 1st amendment

2/6/30

17

WD 066—GPB—30,000—26-7-29

1st Dompad 16

Serial No.	
	19 Bldg Sched for Construction C.E. Mtx 5/6/30 6/6/30 20 Jun 30 B/6
8.	to Sec — Chief Engr " Mtz Const " Comptroller " Consulting Architect & Sec Engr No 2716-99 9-6-30 Sanction the request in dl. for a period

B+S
MEA
2/7/30

10 FEB

No. 9676

Enc. 3

Iic Works Department,

Central Office,

Dated, Bangalore, 8 **February** 1930..

From RAJASEVASAKTA

J. BHORE, Esq., A.M.I.C.E., Etc.,

Chief Engineer of Mysore,

Bangalore.

SECTT. 12 FEB 1930 1257

To

RAJASEVAPARAYANA

B. Srinivasa Iyengar, Esq., B.A., B.L.,

Financial Secretary to Government,

Bangalore.

Subject:- Restoration of Belur and Halebid Temples in the Hassan District.

- - - - - - - - - -

Sir,

With reference to correspondence ending with G.O.No.2775-7 Muz.431-28-2 dated the 20th June 1929, I have the honour to forward herewith a copy of letter No.103 dated the 27th July 1929, together with copies of its enclosures, received from the Superintending Engineer, Shimoga Circle, bringing to notice that a great deal of work is yet to be done in Belur Temple alone as per programme put up. According to the rate at which work is now being done, it is stated that it might take more than 10 years to completely work out the programme, taking into consideration the quantity of work to be done.

2. The Superintending Engineer ~~is~~ therefore requests sanction to the existing establishment at Belur being increased by one more Mason on Rs.40/- and two more coolies on Rs.15/- each per mensem, with an additional money grant of Rs.500/- for materials. This may be sanctioned.

I have the honour to be,

S i r,

Your most obedient servant,

Chief Engineer of Mysore.

hRR/6th.

JEC

Section Lunglai
File No. 249-29
Serial No. 2
No. 1816/Revs

Diary No. of letter replied to 1257

General and Revenue Secretariat
(Lunglai)
the *192*

To
The Lunglai Council
in Impose, Aizawl.

Date of issue 3-3-30

Signed by Mr. G. K. Sing

Sir,
I am directed to forward herewith a copy of letter no 4678 dated the 8th received February, 1930, from the Chief Engineer of Imphal together with ~~Copies~~ its enclosures in original, to be returned with

List of enclosures

Copied by

Examined by

over

WD 063—GPB—20,000—1-8-29

account augment
the Special establish-
ment sanctioned for
the despatch and re-
novation of the
Sri Chamakurva
Army temple at
Bethe, and to request
you to be so good
as to favour Govt
with your opinion
on the Chief Engineer's
proposal contained
in para 2 of his letter
dated 8th July 1930

The favour of an
early reply is re-
quested.

I have etc

JW 28/7

Secy to Govt

[illegible]

24/7/30

OFFICE OF THE MUZRAI COMMISSIONER IN MYSORE

Bangalore, 9th May 1930.



No. 1297 Enclosure 29-30

FROM

Rajakaryapravina
P. G. D'SOUZA, ESQ., B.A., B.L.,
Muzrai Commissioner in Mysore.

12
1797

To

Rajasevaparaj
B. Srinivasa Iyengar, Esq., B.A., B.L.,
Secretary to the Government of His
Highness the Maharaja of Mysore.
Financial Department.

Muz 249-29-3

SIR,

With reference to your letter No.1814/Muz.249-29-2 dated 3rd March 1930 calling for my opinion on the Chief Engineer's -- proposal to augment the existing establishment for the preservation of Belur temple I have the honor to state that a sum of Rs.2144/- per annum is being now spent for the establishment. Of this, item - No.1 amounting to Rs.144 is met from the General Muzrai Fund and items 2 & 3 amounting to Rs.2000/- are met from the annual grant for construction and ---- repairs of Muzrai Institutions.

1. One watchman on Rs.12/- per mensem	Rs.144
2. Special establishment	Rs.1,500
3. Tools & materials	Rs. 500
Total.	Rs. 2,144/-

The additional amount now proposed by the Chief Engineer for the entertainment of one - mason, two coolies and Rs.500/- for materials comes to Rs.1340/- per annum. I am of opinion that that the additional amount may be sanctioned to complete the renova ion work early and that the whole amount of Rs.3484/- may be ordered to be met from the grant of Rs.30,000/- allotted annually from the State & General Muzrai Fund Budgets for the construction and repairs of Muzrai institutions ~~and~~ as the resources of the General Muzrai Funds do not permit -- of any charges in this behalf.

The Chief Engineer's letter together with its

are returned herewith.

I have the honor to be,

Sir,

Your most obedient servant,

Assistant Commissioner,
For Muzrai Commissioner.
(Sbsent from station.)

Letter No.103 dated the 27th July 1929, from the Superintending Engineer, Shimoga Circle, to the Chief Engineer of Mysore, Bangalore.

Restoration of Belur and Halebid Temples, Hassan District.

With reference to your Memo No.10581 dated the 1st June 1929, forwarding copy of Government Consulting Architect's D.O.letter No. 310 dated the 10th May 1929, about the Special Establishment sanctioned for the above purpose, having retained at Belur temple only till the end of December 1929, for the reasons given therein, I have the honour to submit herewith for your kind information, copies of the correspondence ending with Hassan Division Executive Engineer's Memo No.1485 dated the 20th June 1929 together with a copy of the programme of works to be done to the Belur Temple and the strength of the Special Establishment and funds required for Belur temple, as per proposals narrated in person to the First Member of Council, by the Assistant Engineer, in charge of Saklespur P.W.Sub Division, during the former's visit to the Belur and Halebid Temples on the 20th May last. In Government Order No.2775-77/Muz.431-28-2 dated the 20th June 1929, Government have since sanctioned the establishment to be entertained separately for Halebid temple and necessary action will be taken.

It will be seen from the programme that the works to be done in Sri Chennakesavaswamy's temple at Belur are many and are likely to take some years before they are completed. It is absolutely necessary to have additional special establishment and extra funds as applied for by the Executive Engineer to cope with and complete the works much earlier, and I request sanction thereto.

"C o p y."

2/30

for Chief Engineer of Mysore.

mmt/6th.

Letter No.1538 dated 19/24 June 1929, from the Assistant Engineer, No.3 Sub Division, Saklespur to the Executive Engineer, Hassan Division.

With reference to your Memo No.1263 dated 4-6-29 forwarding in original Memo No.8517 dated 29-5-29 from the Superintending Engineer, Shimoga Circle, addressed to you regarding certain proposals of mine submitted in person to the First Member of Council with regard to works in the temples of Belur and Halebid, vide my Memo No.1392 dated 25-5-29, I have the honour to state that it will be treading upon the beaten track and trying to force open a broken door if I were to recount the immense national treasure which we unconsciously possess in the World famous temples of Belur and Halebid I say "unconsciously" above because it exhausts ones patience to hear the criticisms of "nggleot" hurled against such unworthy descendants of such magnanimus forefathers, who brought such grand structures into existence. People from all over the world - civilised countries of eastern and western Hemispheres of the Globe are continuously paying visits to these cynosure of temple architecture and will be simply lost in admiration.

Inspite of the Government of India Act:- The preservation of Ancient Monuments - it is very unfortunate indeed that no tangible work was done towards the renovation of these structures until very recently when with the advent of kind visit of our present Dewan Saheb in March 1927 to Belur, it was ordered that the renovation work must be taken up at once and as a preliminary step a small establishment consisting of two Masons, one male cooly and two female coolies together with a small money grant for purchasing of some materials, was sanctioned in the month of November of the same year. This establishment according to Government Order has to work both the temples at Belur and Halebid. The Masons and coolies are working from the last one year and odd in Belur temple alone and from the programme of works drawn up by me sometime back (copy enclosed for reference) it may be seen that there still remains a good

deal of work to be done in Belur temple alone. At the rate we are going on with the work now, I opine that we require more than ten years to completely work out the programme which is by no means complete considering the grand structures and the quantity of work remaining to be attended to. I therefore submit that the present establishment at Belur increased by one more Mason on Rs.40/- and two more coolies on Rs.15/- each per mensem with an additional money grant of Rs.500/- for materials. Further an entirely separate establishment may kindly be sanctioned for Halebid temple consisting of two Masons on Rs.50/- each, one male cooly on Rs.15/- and two female coolies at Rs.7-8-0 each per mensem together with a money grant of Rs.500/- for materials to start with.

If the above suggestions approved and the new establishment sanctioned, it might be possible to show some substantial work in the renovation works in both the temples.

A comparative statement of the existing and proposed establishment is appended for reference.

Belur Temple.

Existing.		Proposed.	
Name.	Monthly rate.	Name.	Monthly rate.
1 Mason.	60/-	1 Mason	60/-
1 Mason	40/-	1 Mason	40/-
1 Male cooly 0-8-0 to 0-10-0 a day.		3 Coolies 0-8-0 to 0-10-0 a day.	
2 Female coolies 0-4-0 to 0-6-0 a day.		2 Female coolies 4 annas to 6 annas a day.	
Money grant	Rs.500/-	Money grant Rs. 1,000/-	

Halebid Temple.

Nil.		2 Masons.	Rs.50/-
		1 male cooly 0-8-0 to 0-10-0 a day.	
		2 female coolies 4 annas to 6 annas a day	
		Money grant Rs.500/-.	

"C o p y."

K.P.Rao 7/2/30

for Chief Engineer of Mysore.

HRR/6th.

Programme of work in Sri Chennakesavaswamy Temple at Belur.

1. Resetting the stones in front of Mahadwara.
2. Resetting the Sri Chakra.
3. Resetting flooring inside the Navaranga and Sukhanasi room of Kesava Temple.
4. Cement pointing cracks in Sukhanasi door way.
5. Cement pointing crevices in the horizontal fruizes to Kesava temple.
6. Cement pointing crevices at the roof to prevent rain water from getting into the walls.
7. Extending the water spouts of Kesava temple so as to prevent rain water from flowing over the Madanikas.
8. Widening the front door of Kesava temple and cement pointing the ugly crevices.
9. Clearing the fungus growth on the pot stones of the temple buildings.
10. Oiling the images and experimenting how it acts.
11. Replacing fallen bifluxnal cornice and other cornices with reinforced concrete mouldings.
12. Removing the disfigured images in ear like niches and pavilions.
13. Pointing the joints on the lower stones of the stones of the roof so as to prevent leakages which damage the Madanikas.
14. To prevent from falling one of the Madanikas.
15. Filling the cracks with cypsum pressed in by means of thin trowels in pillars.
16. Fixing ~~Rikking~~ the loose pillars firmly in their base.
17. Cement washing the surface of stones where they are decaying.
18. Dismantling Sree Ranganathaswamy's and Sri Narasimhaswamy's temples (projections in Sree Chakra) and resetting Sree Chakra near Narasimhaswamy's temple.
19. Effect on drainage of the temple court yard.
20. Cement pointing the vertical walls of the Sree Chakra

Kappe Channigaraya's Temple.

21. Providing a shutter with perforations for the door way of Garbhagudi.
22. Providing wire netting for holes in the perforated ornamental screens and the doorway to prevent bats from entering in.
23. Cement pointing and other usual repairs to the outer wall.
24. Resetting the basement (Sri Chakra) in the rear to proper level and excavating drain all round, lining them with rough stones.
25. Providing as many outlets as possible from the temple court yard to out side.

26. Repairing the biflexnal cornice.

Sugreeva's Temple.

27. Fixing door shutter of thick planks with ornamental perforations in the top way.

28. Cleaning the Kalasam over the front gopuram.

29. Painting the wood work of niches of Gopuram with Chacolate.

30. Inserting springs in the door shutters, top pieces to act as buffers for taking up shocks while closing the doors with a bang.

Main Temple.

31. Removing the ugly stone supports in the Navaranga and supportin the cracked beams either by angle irons or by the use of iron stirrups and bolts.

32. Building parapet wall over the Garbha Gudi.

33. Removing the ugly stone pillars and cast iron lamp posts on the Sree Chakram.

34. Cleaning and oiling the stones (pillars) images and ceiling stones including the central in the Navaranga. This should be repeatedly done.

35. Removal of Homagunda in the Navaranga.

Naganayakana Mantapam.

36. Replacing of cracked capitals.

37. Replacing of cracked pillars.

38. Cleaning thick coats of white wash, etc., all over the lintels and ceiling.

Kalyana Mantap.

39. Repairing or putting down the three front ankanas and making them vertical two pillars which are out of plum.

Store and Kitchen.

40. Improving the verandah running in front to the entire length.

41. Providing good ventilation to the kitchen.

42. Removing the modern window of the kitchen and blocking with soiled wall to improve the facade of the temple.

43. Providing good paving to the interior of the kitchen.

Ane Bagilu.

44. Repairing the capital of one of the pillars in front of the door way or propping up by means of stone pillars (two pillars may be used to make the thing symetrical.

45. Resetting stone flaggings of the pials and providing a new lovey stone.

Yagasala.

46. Removing the modern window and replacing it by perforated screens and other arrangement for good ventilation.

Pagade Chari Mantap.

47. Repairing the leaky roof.

Sree Ramadevara Sannidhi.

48. Resetting the front steps.

49. Repairing the sinking foundation in front.

Jeeyar Sannidhi.

50. Resetting floor slabs in front of the Mantap.

51. Providing entrance with suitable shutters.

Kappe Chennigarayar Temple.

52. Pannelled ornamental door for the entrance.

53. Resetting slabs on the jagli inside.

Hanumanavara Sannidhi.

54. Replacing modern windows by perforated screens.

Vahana Mantap.

55. Levelling and resetting the pial in front.

56. Repairs to walls.

57. Replacing the iron railing with neat ornamental, dwarf wall, either of perforated stones or brick or even wooden screens.

58. Paving the flooring.

Veeranarayana Temple.

59. Removing thick coat of white washing, etc., on the walls and images.

60. Resetting platform.

61. A new ornamental door.

62. Preventing roof water from flowing over walls by providing sufficient number of water spouts.

Granuary.

63. Repairing the bulged out portion of the wall to the right of the entrance and tidying up the inside.

Andal Sannidhi.

64. Removing the dwarf wall in front and supporting the superstructure by suitable method.

Gajendra Moksha Kalyani or Vasuda Pond.

65. Slight repairs here and there.

66. Raising parapet wall at side with suitable stone wall of proper design.

67. Providing ornamental door to entrance of the Mantap.

68. Setting right the displaced stones and clearing of the two on the landing.

The Mantap in front of Hanumanvara Sannidhi.

69. Steps to be reconstructed.

70. Flooring to be reset and a new parapet wall constructed.

The Gopuram.

71. General repairs here and there.

72. The lovely moulding of some of the niches are broken and should be repaired.

73. The Kalasam requires repairs.

74. Wood works of the Gopuram require renewal.

W e l l.

75. The ground all round should be sloped to drain off water thrown near it.

Garuda Gamba.

76. A straight wooden post is required.

77. Cleaning the metal.

Nagara Khana.

78. Either complete removal or good improvement of the existing structure is necessary to improve the appearance of facade.

Compound Wall.

79. The compound wall has fallen in two places, it should be repaired.

Court Yard of the Temple.

80. The pavement should be reset to the proper level. This requires one complete year.

81. All the inscription stones must be assembled in a suitable place.

82. There are several pieces of stones belonging to different architectural members. They should be assorted and arranged in one place.

The Facade.

83. Removing the thatched car shed repairing or removing the dilapidated Nagarkhana, removing the glazed windows, levelling the ground, removing the motor niche, removing the rubbish

84. Having an ornamental green vedge in the space between Gopuram and Anebagilu.

G e n e r a l.

G e n e r a l.

Preservation of the stone from decay. This is most important.

(Sd) L.Rangaswami Iyer,
Assistant Engineer.

(Sd) N.Krishna Iyengar,
Executive Engineer,
Hassan Division.

"Copy"

(Sd) R.W.Scaldwell,

Superintending Engineer,
Shimoga Circle.

- - - - - - - - - - - - -

"C o p y."

Krishi, 2/20
for Chief Engineer of Mysore.

PRR/6th.

PROCEEDINGS OF THE GOVERNMENT OF HIS HIGHNESS THE MAHARAJA OF MYSORE.

Read :—

Letter No. 9078 dated the 8th February 1930 from the Chief Engineer of Mysore, requesting sanction to the existing special establishment at ~~the~~ Belur being increased by one more mason on Rs. 40/- per mensem and two more coolies on Rs. 15/- each per mensem with an additional money grant of Rs. 500/- per annum for materials to enable the work being completed early.

2. Correspondence ending with letter No. 1207 of 1929-30 dated the 9th/10th May 1930 from the Muzrai Commissioner in Mysore stating that a sum of Rs. 2144/- per annum is being spent for the existing establishment, Rs. 144/- being met from the General Muzrai Fund and the balance of Rs. 2000/- from the annual grant for construction and repairs of Muzrai institutions and recommending that the additional sum of Rs.134 now asked for may be sanctioned and the entire sum of Rs. 3484/- ordered to be met from the annual grant of Rs. 50,000/- from the State and the General Muzrai Fund Budgets for the construction and repairs of Muzrai Institutions.

Order No. 2796-9 Mug 249-29-8

Dated, Bangalore, the 6/7th June 1930.

The recommendation of the Chief Engineer concurred in by the Muzrai Commissioner will be sanctioned for a period of 2 years, the total cost being met as suggested by the Muzrai Commissioner. Quarterly progress reports of works executed to the temple should be continued to be submitted regularly by the Chief Engineer.

For Secretary to Government,
Financial Department.

To
The Chief Engineer of Mysore.
The Muzrai Commissioner in Mysore.
The Comptroller to the Government of Mysore.
The Consulting Architect to the Government of Mysore.

C.P.G.S.

.R.S. App. F VI G-2]

SUBJECT..... .....

.....

... .

Diary No. of letter replied to....1797.....

Sec Dungan

File No. 268-9

Serial No. 4.8

General and revenue Secretariat

(Dungan)

the *192* .

Proceedings of the Government of
His Highness the Maharaja of Mysore.

Read—

Date of issue.....9.6.30.....

Signed by...M.V.T.K.(illegible)...

Letter No 9678 dated the 8th February 1930 from the Chief Engineer of Mysore requesting sanction to the existing special establishment at the Bababudan temple, being increased by one more Mason on Rs 40/- p.m. one Mason and two Dhobi Coolies on Rs 15/- p.m.

Order Thereon No.

May this be

i Printed ?

ii treated as a standing order ?

iii published in the Gazette, English Part ?

iv translated ?

v placed at the disposal of the press ?

vi published in the Gazette, Kannada Part ?

with an additional
money grant of Rs 500/-
per annum for materials
to enable the work being
completed early.
3.
(2) Correspondence
ending with letter No
1297 dated the 9th/10th
29-30
May 1930 from the
Inspector General of Forests
stating that a sum of
Rs 2144 per annum is being
spent for the existing
establishment, Rs 1644/-
being met from the General
Irrigation Fund and the
balance of Rs 500/-
from the annual
grant for construction
and repairs of irrigation
installations and stating
that the ~~sanctioned~~ Copied by
sum of Rs 1340 now Examined by
asked for may be
accordingly sanctioned
the entire sum of Rs 3484/-

List of enclosure.

WD 0326—GPB—12,500—26-5 27

G. R. S. App F. G. 3.

GENERAL AND REVENUE SECRETARIAT.

(Continuation sheet draft form.)

~~three~~ allotted for the purpose ~~mentioned~~ ~~above~~ ~~is~~ ~~proposed~~ ~~to be met~~ from the annual grant of Rs 30,000 from the State & the General Imrazai Fund keeping for the Curtailment and cessation of Imrazai liabilities

2796-9.99 6/30

The recommendation of the Chief Engineer Communicated in by Mr Mayor will be sanctioned for a period of 2 years, the total cost being met as suggested by Mr Mayor

~~Recommendation~~ ~~of~~ ~~the~~ ~~Chief~~ ~~Engineer~~ ~~for~~ ~~a~~ ~~period~~ ~~of~~ ~~2~~ ~~years~~ ~~in~~ ~~the~~ ~~first~~ ~~instance~~ ~~is~~ ~~agreed~~ ~~to~~ ~~by~~ ~~the~~ ~~Commissioners~~ ~~in~~ ~~Council~~ ~~and~~ ~~the~~ ~~cost~~ ~~will~~ ~~be~~ ~~met~~ ~~from~~ ~~the~~ ~~annual~~ ~~grant~~ ~~of~~ ~~Rs~~ ~~30,000~~ ~~from~~ ~~the~~ ~~State~~ ~~&~~ ~~the~~ ~~General~~ ~~Imrazai~~ ~~Fund~~ ~~keeping~~ ~~for~~ ~~the~~ ~~curtailment~~ ~~and~~ ~~cessation~~ ~~of~~ ~~Imrazai~~ ~~liabilities~~ ~~in~~ ~~the~~ ~~first~~ ~~instance~~

~~The~~ ~~cost~~ ~~of~~ ~~the~~ ~~Special~~ Extn and tools and making up Rs 3454 4a. will be met from the annual grant of Rs 30000 as suggested by the Inamrai Commissioners.

~~Recommendation~~ ~~of~~ ~~the~~ Chief Engineer's proposal for a ~~period~~ of 2 years in the first instance ~~is~~ ~~agreed~~ ~~to~~ ~~by~~ ~~the~~ ~~Commissioners~~ ~~in~~ ~~Council~~ ~~and~~ ~~the~~ ~~cost~~ ~~will~~ ~~be~~ ~~met~~ ~~from~~ ~~the~~ ~~annual~~ ~~grant~~ ~~of~~ ~~Rs~~ ~~30,000~~ ~~from~~ ~~the~~ ~~State~~ ~~&~~ ~~the~~ ~~General~~ ~~Imrazai~~ ~~Fund~~ ~~keeping~~ ~~for~~ ~~the~~ ~~curtailment~~ ~~and~~ ~~cessation~~ ~~of~~ ~~Imrazai~~ ~~liabilities~~ ~~in~~ ~~the~~ ~~first~~ ~~instance~~

WD 0327—GPB—10,000—18 5 27

By the Chief Engineer

W. J. Hedley Lieut.

To the Chief Engineer
of my ship.
The Commanding Officer
of my ship
The Commanding Officer of Artillery
Section of the Corps

S.C. 1908
5/6/10
10/-